

Richard Noble Bushfire Attack Level (BAL) Compliance Report Stage 6 Vivente Estate, Hammond Park, WA

8 July 2022 62957/ 145,663 (Rev 0) JBS&G Australia Pty Ltd T/A Strategen-JBS&G



www.jbsg.com.au



## **Table of Contents**

| 1. | Introduction1 |             |  |    |  |
|----|---------------|-------------|--|----|--|
|    | 1.1           | Site/dev    | elopment summary                               | 1  |  |
|    | 1.2           | Purpose     | of report                                      | 1  |  |
| 2. | Bushf         | fire assess | sment results                                  | 3  |  |
|    | 2.1           | Assessm     | ent inputs                                     | 3  |  |
|    |               | 2.1.1       | Vegetation classification                      | 3  |  |
|    |               | 2.1.2       | Effective slope                                | 3  |  |
|    |               | 2.1.3       | Summary of inputs                              | 3  |  |
|    | 2.2           | Assessm     | ent outputs                                    | 6  |  |
|    |               | 2.2.1       | Bushfire Attack Level (BAL) contour assessment | 6  |  |
|    |               | 2.2.2       | BAL certificates                               | 7  |  |
| 3. | Concl         | usion and   | d recommendations                              | 9  |  |
| 4. | Refer         | ences       |  | 10 |  |
| 5. | Limita        | ations      |  | 11 |  |

## List of Tables

| Table 1: Site/development summary  | 1 |
|--|---|
| Table 2: Summary of vegetation classifications, exclusions and effective slope | 4 |
| Table 3: BAL contour assessment results  | 6 |

# List of Figures

| Figure 1: Vegetation classification and effective slope | .5 |
|---|----|
| Figure 2: BAL contour map                               | .8 |

## Appendices

| Appendix A | BAL certificates                       |
|------------|--|
| Appendix B | Vegetation plot photos and description |



## 1. Introduction

### 1.1 Site/development summary

Table 1 provides a summary of the site and proposed development. The development layout and subject lots are shown in Figure 1 and Figure 2.

#### Table 1: Site/development summary

| Site details                  |   |  |  |  |  |
|-------------------------------|---|--|--|--|--|
| Address details               | 48 proposed residential lots within Stage 6 Vivente Estate, Hammond Park WA     |  |  |  |  |
|                               | 6164  |  |  |  |  |
| Local government area         | City of Cockburn  |  |  |  |  |
| Description of building works | Construction of a single residential dwelling (Class 1a building and associated |  |  |  |  |
|                               | Class 10a buildings) within each lot  |  |  |  |  |

#### **1.2** Purpose of report

This Bushfire Attack Level (BAL) compliance report has been prepared for 48 proposed residential lots within Stage 6 Vivente Estate (hereafter referred to as the project area).

All proposed lots except for Lots 147 and 173 are situated within a designated bushfire prone area on the Map of Bush Fire Prone Areas (DFES 2021, see Plate 1). As such, bushfire risk considerations and BAL assessment are required for the 46 designated bushfire prone lots within the project area to facilitate future building approvals.

This report provides a post-subdivisional works update of the Bushfire Attack Level (BAL) ratings for individual lots within the project area and has been prepared for the benefit of the developer, future lot purchasers and decision makers. BAL certificates for each individual lot (contained in Appendix A) have been prepared based on the final site compliance check and are appended to this report to facilitate future lot sales and building approvals.

The BAL assessment outlined in this report has been prepared in consideration of previous BAL contour assessments documented in the Bushfire Management Plans (BMPs) prepared to accompany the Local Structure Plan (LSP) (Strategen 2013, 2015) and LSP amendment (Strategen-JBS&G 2020) for the development. The approach for preparation of this BAL compliance report is consistent with Section 4.2 and Appendix 3 of *Guidelines for Planning in Bushfire Prone Areas* (the Guidelines; WAPC 2021).

The BAL assessment outlined in this report is the most up to date assessment by Strategen-JBS&G relating to the project area and therefore supersedes any previous Strategen/Strategen-JBS&G assessments undertaken within the project area, including those documented in the following previously prepared reports:

- Fire Management Plan for Barfield Road Local Structure Plan, prepared by Strategen (2015)
- Bushfire Management Plan Amendment for Vivente Estate Structure Plan, including Stages 9 and 10, prepared by Strategen-JBS&G (2020).
- Bushfire Management Plan BAL Compliance report Stage 4 Prepared by Strategen-JBS&G August 2020
- Bushfire Management Plan BAL Compliance report Stage 8 Prepared by Strategen-JBS&G September 2021
- Bushfire Management Plan BAL Compliance report Stages 9 and 12 prepared by Strategen-JBS&G November 2021.
- Bushfire Management Plan BAL Compliance report Stages 8 and 9 interface lots prepared by Strategen-JBS&G February 2022.






Plate 1: Map of Bush Fire Prone Areas (DFES 2021)



## 2. Bushfire assessment results

#### 2.1 Assessment inputs

#### 2.1.1 Vegetation classification

Strategen-JBS&G assessed classified vegetation and exclusions within the 150 m assessment area through on-ground verification on 17 May 2022 in accordance with AS 3959—2018 *Construction of Buildings in Bushfire-Prone Areas* (AS 3959; SA 2018) and the *Visual Guide for Bushfire Risk Assessment in Western Australia* (DoP 2016). Georeferenced site photos and a description of the vegetation classifications and exclusions are contained in Appendix B and depicted in Figure 1.

Site observations indicate that the vegetation classifications generally align with the postdevelopment vegetation classifications determined by the endorsed BMPs, except for:

Classified vegetation in the form of Class D scrub and Class G grassland was identified to the east and northeast of the project area. This vegetation was previously assessed as Class B woodland, which is an outdated classification that is no longer appropriate for a predominant banksia scrub fuel profile.

All remaining land situated within 150 m of the project area was identified to be excluded from classification as a result of Stage 6 subdivisional works, construction of adjacent development stages and roadside clearing along Barfield Road. The following exclusions were observed:

- the project area is in a cleared, non-vegetated state in preparation for development and is excluded from classification under Clauses 2.2.3.2 (e) and (f)
- existing non-vegetated and low threat managed land surrounding the project area, including land cleared for future development, existing residential development and low threat managed POS/landscaped areas, excluded under Clauses 2.2.3.2 (e) and (f).

On-site POS has been excluded under Clause 2.2.3.2 (f) as low threat vegetation due to the fragmentation of the vegetation cells and lack of fuel carrying capacity within the vegetation, as previously adopted by the City and DFES under the approved BMPs for Vivente estate.

#### 2.1.2 Effective slope

Strategen-JBS&G assessed effective slope under classified vegetation within the 150 m assessment area through on-ground verification on 17 May 2022 in accordance with AS 3959. Results were cross-referenced with DPIRD 2 m contour data and are depicted in Figure 1.

Site observations indicate that effective slope under the classified vegetation aligns with the effective slopes identified within the endorsed BMPs. Classified vegetation within the assessment area is situated on flat or upsloping land in relation to the project area, resulting in an effective slope of flat/upslope (i.e. 0 degrees).


#### 2.1.3 Summary of inputs

Figure 1 illustrates the current post-development vegetation classifications and exclusions observed during the inspection. The vegetation classifications/exclusions and effective slope are summarised in Table 2.



## Table 2: Summary of vegetation classifications, exclusions and effective slope

| Vegetation plot | Vegetation<br>classification   | Effective slope   | Comments  |
|-----------------|--|-------------------|---|
| 1               | Class D Scrub  | Flat/upslope (0°) | Scrub vegetation predominantly 2–6 m in height with a continuous horizontal fuel profile consisting predominantly of banksia/sheoak.  |
| 2               | Class G Grassland  | Flat/upslope (0°) | Unmanaged grassland vegetation greater than 100 mm in height.   |
| 3               | Excluded – Non-<br>vegetated and Low<br>threat (Clause 2.2.3.2<br>[e] and [f]) | N/A               | Existing non-vegetated areas (i.e. roads, buildings, cleared vacant lots, driveways, footpaths) and low threat managed vegetation (i.e. mowed grass, managed gardens/POS, etc). |



File Name: \\008PMPMR004V001.jbsg.aust\JBS Perth\Projects\1)Open\Richard Noble\62957 Vivente Stage 6 BAL compliance\GIS\Maps\R01\_Rev\_A\62957\_01\_VegClass.mxd Image Reference: www.nearmap.com@ - Imagery Date: 05 April 2022.



#### 2.2 Assessment outputs

#### 2.2.1 Bushfire Attack Level (BAL) contour assessment

Strategen-JBS&G has undertaken a BAL contour assessment in accordance with Method 1 of AS 3959 for the project area (Figure 2). The Method 1 procedure incorporates the following factors:

- state-adopted FDI 80 rating
- vegetation classification
- effective slope
- distance maintained between proposed development areas and the classified vegetation.

The BAL contours are based on the current on-ground site conditions confirmed during site assessment and results are detailed in Table 3 and illustrated in Figure 2.

|     | Bushfire | Vegetation | Vegetation     | Effective along   | Separation |             |
|-----|----------|------------|----------------|-------------------|------------|-------------|
| Lot | prone    | plot       | classification | Effective slope   | distance   | Highest BAL |
| 79  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 80  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 81  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 82  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 83  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 84  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 85  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 86  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 87  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 88  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 89  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 90  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 91  | Yes      | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 92  | res      | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 93  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 94  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 95  |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 116 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 117 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 118 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 119 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 120 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 121 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 122 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 123 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 124 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 147 | No       |            |                | N/A               |            |             |
| 148 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 157 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 158 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 159 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 160 |          | 1          | Class D Scrub  | Flat/upslope (0°) | 90 m       | BAL-12.5    |
| 161 | Yes      | 1          | Class D Scrub  | Flat/upslope (0°) | 79 m       | BAL-12.5    |
| 167 | Yes      | 1          | Class D Scrub  | Flat/upslope (0°) | 55 m       | BAL-12.5    |
| 168 |          | 1          | Class D Scrub  | Flat/upslope (0°) | 70 m       | BAL-12.5    |
| 169 |          | 1          | Class D Scrub  | Flat/upslope (0°) | 82 m       | BAL-12.5    |
| 170 |          | 1          | Class D Scrub  | Flat/upslope (0°) | 94 m       | BAL-12.5    |
| 171 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 172 |          | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |
| 173 | No       |            | T              | N/A               | -          | -           |
| 371 | Yes      | 1          | Class D Scrub  | Flat/upslope (0°) | >100 m     | BAL-Low     |


#### Table 3: BAL contour assessment results



| Lot | Bushfire<br>prone | Vegetation<br>plot | Vegetation<br>classification | Effective slope   | Separation<br>distance | Highest BAL |
|-----|-------------------|--------------------|------------------------------|-------------------|------------------------|-------------|
| 372 |                   | 1                  | Class D Scrub                | Flat/upslope (0°) | >100 m                 | BAL-Low     |
| 428 |                   | 1                  | Class D Scrub                | Flat/upslope (0°) | 66 m                   | BAL-12.5    |
| 429 |                   | 1                  | Class D Scrub                | Flat/upslope (0°) | 55 m                   | BAL-12.5    |
| 430 | Yes               | 1                  | Class D Scrub                | Flat/upslope (0°) | >100 m                 | BAL-Low     |
| 431 |                   | 1                  | Class D Scrub                | Flat/upslope (0°) | >100 m                 | BAL-Low     |
| 432 |                   | 1                  | Class D Scrub                | Flat/upslope (0°) | >100 m                 | BAL-Low     |
| 433 |                   | 1                  | Class D Scrub                | Flat/upslope (0°) | >100 m                 | BAL-Low     |

#### 2.2.2 BAL certificates

BAL certificates are provided in Appendix A in accordance with the BAL contour assessment results detailed in Table 3 and Figure 2.





## 3. Conclusion and recommendations

This BAL compliance report has been prepared for 48 proposed residential lots within Stage 6 Vivente Estate to provide a final BAL check and certification for individual lots for use at the building permit stage. A BAL certificate has been prepared for each of the 46 proposed lots situated within a designated bushfire prone area, noting that proposed Lots 147 and 173 are not situated within a designated bushfire prone area and therefore do not require any further bushfire risk consideration or BAL assessment to facilitate future building approval.

Assessment results are consistent with current on-ground conditions confirmed during site assessment. Strategen-JBS&G can confirm that the existing BMPs over the site have been implemented throughout the duration of subdivisional works for the relevant Stage 6 area and adjacent land to achieve the BAL outcomes as intended.

Ongoing requirements of the current City of Cockburn annual firebreak notice should continue to be implemented as required, particularly with regards to ongoing fuel management of vacant land and road reserves.



### 4. References

- Department of Fire and Emergency Services (DFES) 2021, *Map of Bush Fire Prone Areas*, [Online], Government of Western Australia.
- Department of Planning (DoP) 2016, *Visual guide for bushfire risk assessment in Western Australia*, Department of Planning, Perth.
- Standards Australia (SA) 2018, Australian Standard AS 3959–2018 Construction of Buildings in Bushfire-prone Areas, Standards Australia, Sydney.
- Strategen Environmental (Strategen) 2015, *Fire Management Plan: Barfield Road Local Structure Plan*, Strategen, Bunbury.
- Strategen-JBS&G 2020, Bushfire Management Plan: Vivente Estate Structure Plan Amendment, including Stages 9 and 10, Strategen, Bunbury.
- Strategen-JBS&G 2020, *Bushfire Management Plan BAL Compliance report Stage 4 Vivente Estate*, report prepared for Richard Noble, August 2020.
- Strategen-JBS&G 2021, *Bushfire Management Plan BAL Compliance report Stage 8 Vivente Estate*, report prepared for Richard Noble, September 2021.
- Strategen-JBS&G 2021, *Bushfire Management Plan BAL Compliance report Stages 9 and 12 Vivente Estate*, report prepared for Richard Noble, November 2021.
- Strategen-JBS&G 2022, Bushfire Management Plan BAL Compliance report Stages 8 and 9 Interfacing lots, Vivente Estate, report prepared for Richard Noble, February 2022.
- Western Australian Planning Commission (WAPC) 2021, *Guidelines for Planning in Bushfire Prone Areas*, Version 1.4 December 2021, Western Australian Planning Commission, Perth.



## 5. Limitations

#### Scope of services

This report ("the report") has been prepared by Strategen-JBS&G in accordance with the scope of services set out in the contract, or as otherwise agreed, between the Client and Strategen-JBS&G. In some circumstances, a range of factors such as time, budget, access and/or site disturbance constraints may have limited the scope of services. This report is strictly limited to the matters stated in it and is not to be read as extending, by implication, to any other matter in connection with the matters addressed in it.

#### **Reliance on data**

In preparing the report, Strategen-JBS&G has relied upon data and other information provided by the Client and other individuals and organisations, most of which are referred to in the report ("the data"). Except as otherwise expressly stated in the report, Strategen-JBS&G has not verified the accuracy or completeness of the data. To the extent that the statements, opinions, facts, information, conclusions and/or recommendations in the report ("conclusions") are based in whole or part on the data, those conclusions are contingent upon the accuracy and completeness of the data. Strategen-JBS&G has also not attempted to determine whether any material matter has been omitted from the data. Strategen-JBS&G will not be liable in relation to incorrect conclusions should any data, information or condition be incorrect or have been concealed, withheld, misrepresented or otherwise not fully disclosed to Strategen-JBS&G. The making of any assumption does not imply that Strategen-JBS&G has made any enquiry to verify the correctness of that assumption.

The report is based on conditions encountered and information received at the time of preparation of this report or the time that site investigations were carried out. Strategen-JBS&G disclaims responsibility for any changes that may have occurred after this time. This report and any legal issues arising from it are governed by and construed in accordance with the law of Western Australia as at the date of this report.

### **Environmental conclusions**

Within the limitations imposed by the scope of services, the preparation of this report has been undertaken and performed in a professional manner, in accordance with generally accepted environmental consulting practices. No other warranty, whether express or implied, is made.

The advice herein relates only to this project and all results conclusions and recommendations made should be reviewed by a competent person with experience in environmental investigations, before being used for any other purpose.

Strategen-JBS&G accepts no liability for use or interpretation by any person or body other than the client who commissioned the works. This report should not be reproduced without prior approval by the client, or amended in any way without prior approval by Strategen-JBS&G, and should not be relied upon by other parties, who should make their own enquiries.



## Appendix B Vegetation plot photos and description





Photo ID: 1e



|                                       | Plot 2   |
|---------------------------------------|--|
| Vegetation classification             | Class G Grassland  |
|                                       | Flat/Upslope   |
| Description / justification           | Grassland at maturity, greater than 100 mm in height   |
| 270 300                               | IW 330 NE 60   |
| • • • • •                             | •   •   •   •   •   •   •   •   •   •  |
| © 352°N                               | (T)  |
|                                       |  |
| Charles Vie                           |  |
|                                       |  |
|                                       | A CARLES AND A C   |
|                                       |  |
|                                       | and the second sec   |
|                                       |  |
|                                       |  |
|                                       |  |
| A State of the second                 |  |
|                                       |  |
|                                       |  |
| A REAL CONTRACTOR                     | A CONTRACT OF A  |
|                                       | 17 May 2022; 10:15:59  |
| hoto ID: 2a                           | 17 May 2022, 10:13:39  |
| N                                     | 0 NE 60 E SE 120 150   |
| 0 3                                   | 0 60 90 120 150  |
|                                       |  |
| © 71°NE                               | (T) ● -32.177171, 115.853986 ±4 m ▲ 7 m  |
|                                       |  |
|                                       |  |
|                                       |  |
|                                       | and the second secon  |
| service in the                        |  |
| And the second second                 | MARKEN MERICE HIT  |
|                                       | and the second sub-  |
| A A A A A A A A A A A A A A A A A A A | A CONTRACTOR OF THE STATE OF THE STATE OF THE STATE  |
| A A A A A A A A A A A A A A A A A A A |  |
| AND AND A                             |  |
|                                       | State of the state |
|                                       |  |
| A Contraction                         |  |
|                                       |  |
|                                       | 17 May 2022, 10:16:18  |

Photo ID: 2b






Photo ID: 3e

Photo ID: 3f







© JBS&G Australia Pty Ltd T/A Strategen-JBS&G

This document is and shall remain the property of Strategen-JBS&G. The document may only be used for the purposes for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

#### **Document Status**

| Report       | Dev Ne  | Purpose   | Author                                     | Reviewed and Approved for Issue        |             |
|--------------|---------|---|--|--|-------------|
| version      | REV NO. |   |  | Name                                   | Date        |
| Final Report | Rev 0   | Issued for use: to facilitate<br>future lot sales and<br>building approvals | Kaitlin Southgate (BPAD<br>57034, Level 1) | Zac Cockerill (BPAD<br>37803, Level 2) | 8 July 2022 |

