

Richard Noble AS 3959 Bushfire Attack Level (BAL) Assessment Report

Lot 285 Campana Rise, Hammond Park, WA

12 March 2020 56824/128,175 (Rev 0) JBS&G Australia Pty Ltd T/A Strategen-JBS&G



# **Table of Contents**

1.	Site assessment and site plan	.1
2.	Vegetation classification	.1
3.	Relevant Fire Danger Index	.1
4.	Potential bushfire impacts	.2
5.	Determined Bushfire Attack Level (BAL)	.2
6.	Shielding provisions	.2
7.	Limitations	.4

# List of Tables

Table 1: Method 1 Bushfire Attack Level (BA	.) analysis2
---	--------------

# **List of Figures**

Figure 1: BAL assessment
--------------------------

# Appendices

Appendix A	BAL certificate
Appendix B	Vegetation plot photos and description



Site details				
Address	Lot 285 Campana Rise, Hammond Park, WA 6164			
Local government area	City of Cockburn			
Main BCA class of the building	Class 1a			
Use(s) of the building	Residential dwelling			
Description of the building or works	Construction of single residential dwelling and associated Class 10a structure			

Report details					
Project/Document number	56824/128,175	Report reference	Rev O		
Assessment date	15 May 2019	Report date	12 March 2020		

BPAD Accredited Practitioner Details			
Name Zac Cockerill (BPAD 37803, Level 2)			
Endorsement/Review	Zac Cockerill (BPAD 37803, Level 2)		
Company details	JBS&G Australia Pty Ltd T/A Strategen-JBS&G, Perth		

#### 1. Site assessment and site plan

The most recent assessment of this site/development was undertaken on 15 May 2019 by a BPAD Accredited Practitioner for the purpose of determining the Bushfire Attack Level in accordance with AS 3959 - 2018 (Simplified Procedure [Method 1]).

The assessment has been carried out in relation to the cadastral boundaries of the subject lot, rather than to a proposed building footprint, therefore, a Site Plan has not been included with this assessment and the BAL assessment is to the lot boundary. The site assessment results are depicted in Figure 1.

### 2. Vegetation classification

All vegetation within 150 m of the site/development was classified in accordance with Clause 2.2.3.2 of *AS 3959-2018 Construction of buildings in bushfire prone areas* (AS 3959) and the *Visual Guide for Bushfire Risk Assessment in Western Australia*. Each distinguishable vegetation class with the potential to determine the Bushfire Attack Level is identified in Appendix B and in Figure 1.

#### 3. Relevant Fire Danger Index

The fire danger index for this site/development has been determined in accordance with Table 2.1 of AS 3959 or otherwise determined in accordance with a jurisdictional variation applicable to the site.

Fire Danger Index					
FDI 40 🗌	FDI 50 🗌	FDI 80 🖂	FDI 100 🗌		
Table 2.4.5	Table 2.4.4	Table 2.4.3	Table 2.4.2		



### 4. Potential bushfire impacts

The potential bushfire impact to the site/development from each of the identified vegetation plots are identified in Table 1.

#### Table 1: Method 1 Bushfire Attack Level (BAL) analysis

Method 1 BAL determination					
Plot	Vegetation classification	Effective slope	Separation (m)	BAL	
1	Excluded – Clause 2.2.3.2 [c]	N/A	N/A	BAL–Low	
2	Excluded – Clause 2.2.3.2 [d]	N/A	N/A	BAL-Low	
3	Excluded – Non-vegetated and Low threat	N/A	N/A	BAL–Low	
	(Clause 2.2.3.2 [e] and [f])				

## 5. Determined Bushfire Attack Level (BAL)


The Determined Bushfire Attack Level (highest BAL) for the site / proposed development has been determined in accordance with Clause 2.2.6 of AS 3959-2018 using the above analysis.

**Determined Bushfire Attack Level** 

BAL-Low

#### 6. Shielding provisions

Shielding provisions are not applicable as the subject lot is subject to BAL-LOW.



File Name: W:\Projects\1)Open\Richard Noble\56824 Vivente bushfire advice and BAL compliance (RNO19198.01)\GIS\Maps\M03 Rev A\56824\_01\_BAL\_Assessment.mxd Image Reference: www.nearmap.com© - Imagery Date: 09. December 2019.



### 7. Limitations

#### Scope of services

This report ("the report") has been prepared by Strategen-JBS&G in accordance with the scope of services set out in the contract, or as otherwise agreed, between the Client and Strategen-JBS&G. In some circumstances, a range of factors such as time, budget, access and/or site disturbance constraints may have limited the scope of services. This report is strictly limited to the matters stated in it and is not to be read as extending, by implication, to any other matter in connection with the matters addressed in it.

#### **Reliance on data**

In preparing the report, Strategen-JBS&G has relied upon data and other information provided by the Client and other individuals and organisations, most of which are referred to in the report ("the data"). Except as otherwise expressly stated in the report, Strategen-JBS&G has not verified the accuracy or completeness of the data. To the extent that the statements, opinions, facts, information, conclusions and/or recommendations in the report ("conclusions") are based in whole or part on the data, those conclusions are contingent upon the accuracy and completeness of the data. Strategen-JBS&G has also not attempted to determine whether any material matter has been omitted from the data. Strategen-JBS&G will not be liable in relation to incorrect conclusions should any data, information or condition be incorrect or have been concealed, withheld, misrepresented or otherwise not fully disclosed to Strategen-JBS&G. The making of any assumption does not imply that Strategen-JBS&G has made any enquiry to verify the correctness of that assumption.

The report is based on conditions encountered and information received at the time of preparation of this report or the time that site investigations were carried out. Strategen-JBS&G disclaims responsibility for any changes that may have occurred after this time. This report and any legal issues arising from it are governed by and construed in accordance with the law of Western Australia as at the date of this report.

#### **Environmental conclusions**

Within the limitations imposed by the scope of services, the preparation of this report has been undertaken and performed in a professional manner, in accordance with generally accepted environmental consulting practices. No other warranty, whether express or implied, is made.

The advice herein relates only to this project and all results conclusions and recommendations made should be reviewed by a competent person with experience in environmental investigations, before being used for any other purpose.

Strategen-JBS&G accepts no liability for use or interpretation by any person or body other than the client who commissioned the works. This report should not be reproduced without prior approval by the client, or amended in any way without prior approval by Strategen-JBS&G, and should not be relied upon by other parties, who should make their own enquiries.



# Appendix B Vegetation plot photos and description











Photo ID: 2a			
Plot number Plot 2			
Vegetation classification Excluded – Clause 2.2.3.2 [d]			
<b>Description / justification</b> Plot comprises a single strip of vegetation less than 20 m width and not			
	20 m of the subject lot.		











#### © JBS&G Australia Pty Ltd T/A Strategen-JBS&G

This document is and shall remain the property of Strategen-JBS&G. The document may only be used for the purposes for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

#### **Document Status**

Report	· Rev No.	Purpose	Author	Reviewed and Approved for Issue	
version				Name	Date
Final Report	Rev 0	Issued for use: to accompany lot sale and building permit application	Louisa Robertson (BPAD 36748, Level 1)	Zac Cockerill (BPAD 37803, Level 2)	12 March 2020

