

Richard Noble Bushfire Attack Level (BAL) Compliance Report

20 lots within Stages 8 and 9 Vivente Estate Hammond Park, WA

7 October 2022 61728/147,549 (Rev 1) JBS&G Australia Pty Ltd T/A Strategen-JBS&G



www.jbsg.com.au



## **Table of Contents**

1.	Introd	duction		1
	1.1	Site sum	mary	1
	1.2	Purpose	of report	1
2.	Bushf	ire assess	ment results	3
	2.1	Assessm	ent inputs	3
		2.1.1	Vegetation classification	3
		2.1.2	Effective slope	3
		2.1.3	Summary of inputs	4
	2.2	Assessm	ent outputs	6
		2.2.1	Bushfire Attack Level (BAL) contour assessment	6
		2.2.2	BAL certificates	7
3.	Concl	usion and	l recommendations	9
4.	Refer	ences		.10
5.	Limita	ations		.11

## List of Tables

Table 1: Site/development summary	.1
Table 2: Summary of vegetation classifications, exclusions and effective slope	.4
Table 3: BAL contour assessment results	6

# List of Figures

Figure 1: Vegetation classification and effective slope	.5
Figure 2: BAL contour map	.8

## Appendices

Appendix A	BAL certificates
Appendix B	Vegetation plot photos and description



## 1. Introduction

#### 1.1 Site summary

Table 1 provides a summary of the project area and proposed development. The development layout and subject lots are shown in Figure 1 and Figure 2.

#### Table 1: Site/development summary

Site details				
Address details	20 proposed residential lots within Stages 8 and 9 Vivente Estate, Hammond Park WA, 6164			
Local government area	City of Cockburn			
Description of building works	Construction of single residential dwellings (Class 1a building and associated Class 10a buildings) within each lot			

#### 1.2 Purpose of report

This Bushfire Attack Level (BAL) compliance report has been prepared for 20 proposed residential lots within Stages 8 and 9 Vivente Estate (hereafter referred to as the project area), comprising four lots within Stage 8 and 16 lots within Stage 9.

The project area is designated bushfire prone on the Map of Bush Fire Prone Areas (DFES 2021, see Plate 1). As such, bushfire risk considerations and BAL assessment are applicable to all proposed lots within the project area and are required to support future building permit applications.

This report provides a post-subdivisional works update of the Bushfire Attack Level (BAL) ratings for individual lots within the project area and has been prepared for the benefit of the developer, future lot purchasers and decision makers. BAL certificates for each individual lot (see Appendix A) have been prepared based on an updated site compliance check undertaken on 7 September 2022 and are appended to this report for use at the building permit stage to facilitate future lot sales and building approvals.

The BAL assessment outlined in this report has been prepared in consideration of the previous BAL compliance report for the project area (Strategen-JBS&G 2022) and previous BAL contour assessments documented in the Bushfire Management Plans (BMPs) prepared to accompany the Local Structure Plan (LSP) (Strategen 2015) and LSP amendment (Strategen-JBS&G 2020) for the development. The approach for preparation of this BAL compliance report is consistent with Section 4.2 and Appendix 3 of *Guidelines for Planning in Bushfire Prone Areas* (the Guidelines; WAPC 2021).

The BAL assessment outlined in this report is the most up to date Strategen-JBS&G assessment relating to the project area and therefore supersedes any previous Strategen/Strategen-JBS&G assessments undertaken within the project area, including those documented in the following previously prepared reports:

- Fire Management Plan for Barfield Road Local Structure Plan, prepared by Strategen (2015)
- Bushfire Management Plan Amendment for Vivente Estate Structure Plan, including Stages 9 and 10, prepared by Strategen-JBS&G (2020)
- original BAL compliance prepared for 20 lots within Stages 8 and 9 Vivente Estate (Strategen-JBS&G 2022).





Plate 1: Map of Bush Fire Prone Areas (DFES 2021)



### 2. Bushfire assessment results

#### 2.1 Assessment inputs

#### 2.1.1 Vegetation classification

Strategen-JBS&G assessed classified vegetation and exclusions within the 150 m assessment area through on-ground verification on 12 October 2021 and reassessment on 7 September 2022 in accordance with AS 3959—2018 *Construction of Buildings in Bushfire-Prone Areas* (AS 3959; SA 2018) and the *Visual Guide for Bushfire Risk Assessment in Western Australia* (DoP 2016). Georeferenced photos and a description of the vegetation classifications and exclusions are contained in Appendix B and depicted in Figure 1.

The predominant vegetation classification within the 150 m wide assessment area is Class D Scrub, which is identified to the east and south of the project area.

Site observations indicate that the vegetation classifications have evolved following ongoing clearing and earthworks throughout the estate, such that the extent of cleared, low threat land has expanded beyond that determined in previous BMPs and BAL reports (e.g. Strategen-JBS&G 2022). In particular, land clearing to the north of the project area has caused the previously classified Class D scrub vegetation and Class G grassland vegetation (as assessed in Strategen-JBS&G 2022) to become a non-vegetated/low threat area excluded under Clauses 2.2.3.2 (e) and (f).

The 20 m wide cleared firebreak to the east of the project area and 16 m wide cleared low threat staging buffer to the south of the project area continue to be maintained in a low threat state and are excluded under Clauses 2.2.3.2 (e) and (f).

All other land within the 150 m assessment area was confirmed to be excluded from classification as per the following observations:

- the project area is in a cleared, non-vegetated state in preparation for development and is excluded from classification under Clauses 2.2.3.2 (e) and (f)
- existing non-vegetated and low threat managed land surrounding the project area, including land cleared for future development, existing residential development and low threat managed landscaped areas and staging buffers are excluded under Clauses 2.2.3.2 (e) and (f)
- a narrow strip of vegetation fronting Rowley Road that is less than 20 m wide and not within 20 m of other areas of classified vegetation or the site is excluded under Clause 2.2.3.2 (d).

The adjacent west POS cell has been excluded under Clause 2.2.3.2 (f) as low threat vegetation due to the fragmentation of the vegetation cells and lack of fuel carrying capacity within the vegetation, as previously adopted by the City and DFES under the approved BMPs for Vivente Estate.

#### 2.1.2 Effective slope

Strategen-JBS&G assessed effective slope under classified vegetation within the 150 m assessment area through on-ground verification on 12 October 2021 and reassessment on 7 September 2022 in accordance with AS 3959. Results were cross-referenced with DPIRD 2 m contour data and are depicted in Figure 1.

Site observations indicate that effective slope under classified vegetation aligns with the effective slopes identified within the endorsed BMPs, with that being an effective slope of flat/upslope (i.e. 0 degrees).




#### 2.1.3 Summary of inputs

Figure 1 illustrates the current vegetation classifications and exclusions observed during the latest site inspection. The vegetation classifications/exclusions and effective slope are summarised in Table 2.

Vegetation plot	Vegetation classification	Effective slope	Comments	
1 Class D Scrub		Flat/upslope (0°)	Scrub vegetation 2–6 m in height with a continuous horizontal fuel profile.	
2 Excluded – Clause 2.2.3.2 [d]		N/A	Narrow strip of vegetation less than 20 m wide and not within 20 m of other areas of classified vegetation or the project area.	
3	Excluded – Non- vegetated and Low threat (Clause 2.2.3.2 [e] and [f])	N/A	Existing non-vegetated areas (i.e. roads, buildings, cleared vacant lots, driveways, footpaths) and low threat managed vegetation (i.e. mowed grass, slashed staging buffers, managed gardens/POS, etc). Includes central vegetated POS which has been assessed as low threat due to fragmentation and lack of fuel carrying capacity.	

#### Table 2: Summary of vegetation classifications, exclusions and effective slope



File Name: W:\Projects\1)Open\Richard Noble\61728 BAL compliance Stages 9 & 12 Vivente\GIS\Maps\R02\_Rev\_A\61728\_01\_VegClass.mxd Image Reference: www.nearmap.com© - Imagery Date: 30. August 2022.



#### 2.2 Assessment outputs

#### 2.2.1 Bushfire Attack Level (BAL) contour assessment

Strategen-JBS&G has undertaken a BAL contour assessment in accordance with Method 1 of AS 3959 for the project area (Figure 2). The Method 1 procedure incorporates the following factors:

- state adopted FDI 80 rating
- vegetation classification
- effective slope
- distance maintained between proposed development areas and the classified vegetation.

The BAL contours are based on the current on-ground site conditions confirmed during site assessment and results are detailed in Table 3 and illustrated in Figure 2.

Lot	Bushfire prone area	Plot No.	Vegetation classification	Effective slope	Separation distance	Highest BAL	Setback required to achieve lower BAL*	Potential new BAL with setback*
Stage 8								
850		1	Class D Scrub	Flat/upslope (0°)	>100 m	BAL-Low	N/A	N/A
851		1	Class D Scrub	Flat/upslope (0°)	>100 m	BAL-Low	N/A	N/A
884	Yes	1	Class D Scrub	Flat/upslope (0°)	31 m	BAL-12.5	N/A	N/A
885		1	Class D Scrub	Flat/upslope (0°)	16 m	BAL-29	3 m side (south) setback	BAL-19
		1	T	1	Stage 9		1	
852		1	Class D Scrub	Flat/upslope (0°)	>100 m	BAL-Low	N/A	N/A
853		1	Class D Scrub	Flat/upslope (0°)	94 m	BAL-12.5	N/A	N/A
854		1	Class D Scrub	Flat/upslope (0°)	79 m	BAL-12.5	N/A	N/A
855		1	Class D Scrub	Flat/upslope (0°)	64 m	BAL-12.5	N/A	N/A
856		1	Class D Scrub	Flat/upslope (0°)	51 m	BAL-12.5	N/A	N/A
857		1	Class D Scrub	Flat/upslope (0°)	41 m	BAL-12.5	N/A	N/A
858		1	Class D Scrub	Flat/upslope (0°)	30 m	BAL-12.5	N/A	N/A
859		1	Class D Scrub	Flat/upslope (0°)	20 m	BAL-19	N/A	N/A
876		1	Class D Scrub	Flat/upslope (0°)	16 m	BAL-29	3m rear (south) setback	BAL-19
877	Yes	1	Class D Scrub	Flat/upslope (0°)	16 m	BAL-29	3m rear (south) setback	BAL-19
878		1	Class D Scrub	Flat/upslope (0°)	16 m	BAL-29	3m rear (south) setback	BAL-19
879		1	Class D Scrub	Flat/upslope (0°)	16 m	BAL-29	3m rear (south) setback	BAL-19
880		1	Class D Scrub	Flat/upslope (0°)	16 m	BAL-29	3m rear (south) setback	BAL-19
881		1	Class D Scrub	Flat/upslope (0°)	16 m	BAL-29	3m rear (south) setback	BAL-19
882		1	Class D Scrub	Flat/upslope (0°)	16 m	BAL-29	3m rear (south) setback	BAL-19
883		1	Class D Scrub	Flat/upslope (0°)	16 m	BAL-29	3m rear (south) setback	BAL-19

#### Table 3: BAL contour assessment results

\*The new BAL rating can only be confirmed once the building plan for the relevant lot has been prepared to demonstrate compliance with the recommended setback.



#### 2.2.2 BAL certificates

BAL certificates are provided in Appendix A in accordance with the BAL contour assessment results detailed in Table 3 and Figure 2.

Should a lower BAL be realistically achievable through an appropriate building setback, then the landowner can refer to the recommended setbacks listed in Table 3. The lower BAL may be achieved if the recommended building setback is reflected on the building plan for that lot and a revised BAL certificate can be issued at that time.



File Name: W:\Projects\1)Open\Richard Noble\61728 BAL compliance Stages 9 & 12 Vivente\GIS\Maps\R02\_Rev\_A\61728\_02\_BALs.mxd Image Reference: www.nearmap.com© - Imagery Date: 30. August 2022.



## 3. Conclusion and recommendations

This BAL compliance report has been prepared for four residential lots within Stage 8 and 16 residential lots within Stage 9 Vivente Estate to provide a final BAL check and certification for use at the building permit stage.

Following the latest assessment of on-ground conditions on 7 September 2022, Strategen-JBS&G can confirm that the existing BMPs over the project area have been implemented throughout the duration of subdivisional works for the relevant Stage 8 and 9 lots and adjacent land to achieve the BAL outcomes as intended.

Nine lots can potentially achieve a lower BAL if building setbacks are implemented, as set out in Table 3. Should it be determined through demonstration on individual building plans that compliance with the recommended building setbacks has been achieved and subsequently a lower BAL rating has been attained (as per Table 3), then the lower BAL rating should apply and be reflected in an updated BAL certificate prepared at that time.

Strategen-JBS&G considers that the BAL contour assessment and BAL certificates outlined in this report are accurate to inform individual lot building permit applications.



### 4. References

Department of Fire and Emergency Services (DFES) 2021, *Map of Bush Fire Prone Areas*, [Online], Government of Western Australia, available from:

https://maps.slip.wa.gov.au/landgate/bushfireprone/, [7/10/2022].

- Department of Planning (DoP) 2016, *Visual guide for bushfire risk assessment in Western Australia*, Department of Planning, Perth.
- Standards Australia (SA) 2018, Australian Standard AS 3959–2018 Construction of Buildings in Bushfire-prone Areas, Standards Australia, Sydney.
- Strategen Environmental (Strategen) 2015, *Fire Management Plan: Barfield Road Local Structure Plan*, Strategen, Bunbury.
- Strategen-JBS&G 2020, Bushfire Management Plan: Vivente Estate Structure Plan Amendment, including Stages 9 and 10, Strategen-JBS&G, Bunbury.
- Strategen-JBS&G 2022, Bushfire Attack Level Compliance Report: Stages 9 and 12 Vivente Estate, Strategen-JBS&G, Bunbury.
- Western Australian Planning Commission (WAPC) 2017, *Guidelines for Planning in Bushfire Prone Areas, Version 1.4 December 2021*, Western Australian Planning Commission, Perth.



## 5. Limitations

#### Scope of services

This report ("the report") has been prepared by Strategen-JBS&G in accordance with the scope of services set out in the contract, or as otherwise agreed, between the Client and Strategen-JBS&G. In some circumstances, a range of factors such as time, budget, access and/or site disturbance constraints may have limited the scope of services. This report is strictly limited to the matters stated in it and is not to be read as extending, by implication, to any other matter in connection with the matters addressed in it.

#### **Reliance on data**

In preparing the report, Strategen-JBS&G has relied upon data and other information provided by the Client and other individuals and organisations, most of which are referred to in the report ("the data"). Except as otherwise expressly stated in the report, Strategen-JBS&G has not verified the accuracy or completeness of the data. To the extent that the statements, opinions, facts, information, conclusions and/or recommendations in the report ("conclusions") are based in whole or part on the data, those conclusions are contingent upon the accuracy and completeness of the data. Strategen-JBS&G has also not attempted to determine whether any material matter has been omitted from the data. Strategen-JBS&G will not be liable in relation to incorrect conclusions should any data, information or condition be incorrect or have been concealed, withheld, misrepresented or otherwise not fully disclosed to Strategen-JBS&G. The making of any assumption does not imply that Strategen-JBS&G has made any enquiry to verify the correctness of that assumption.

The report is based on conditions encountered and information received at the time of preparation of this report or the time that site investigations were carried out. Strategen-JBS&G disclaims responsibility for any changes that may have occurred after this time. This report and any legal issues arising from it are governed by and construed in accordance with the law of Western Australia as at the date of this report.

#### **Environmental conclusions**

Within the limitations imposed by the scope of services, the preparation of this report has been undertaken and performed in a professional manner, in accordance with generally accepted environmental consulting practices. No other warranty, whether express or implied, is made.

The advice herein relates only to this project and all results conclusions and recommendations made should be reviewed by a competent person with experience in environmental investigations, before being used for any other purpose.

Strategen-JBS&G accepts no liability for use or interpretation by any person or body other than the client who commissioned the works. This report should not be reproduced without prior approval by the client, or amended in any way without prior approval by Strategen-JBS&G, and should not be relied upon by other parties, who should make their own enquiries.



## Appendix B Vegetation plot photos and description






Photo ID: 1c



Plot 2					
Vegetation classification	Excluded – Clause 2.2.3.2 [d]				
Description / justification	Strips of vegetation less than 20 m in width (regardless of length) and not within 20 m of the site or each other or other areas of classified vegetation.				
SW W 240 270 1 • 1 •   •   •	I <mark>IW N</mark> 300 330 0 30 •   •   •   •   •   •   •   •   •   •				
© 312°NW (T)	) ● -32.180715, 115.848385 ±6 m ▲ 6 m				
	Photo ID: 2a				







#### © JBS&G Australia Pty Ltd T/A Strategen-JBS&G

This document is and shall remain the property of Strategen-JBS&G. The document may only be used for the purposes for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Document	Status
----------	--------

Report	Rev No.	Purpose	Author	Reviewed and Approved for Issue	
version			Author	Name	Date
Final Report	Rev 0	Issued for use: to accompany future lot sale and building permit applications	Jasmin Culverwell	Louisa Robertson (BPAD 36748, Level 3)	14 February 2022
Final Report	Rev 1	Issued for use: to facilitate future lot sale and building approvals	Olivia Johnston	Zac Cockerill (BPAD 37803, Level 2)	7 October 2022

